



CALIBRATION CERTIFICATE

DAFCHGX002140003

1 3  
Page 1 of 3 Pages

22

PH

GPP68

201910120100

/

2024-05-06

2024-05-06

2024-05-10



stamp

3

The laboratory address:3/F.,Building3,Zhuguang Chuangxin Science & Technology Park, Zhuguang Road,Taoyuan Street,Nanshan District,Shenzhen,Guangdong,China

Tel g075"

Large stylized watermark 'P' on the left side of the page.

DIRECTIONS OF CALIBRATION

DAFCHGX002140003

2 3  
Page 2 of 3 Pages

Certificate No.

1. 15  
The results is ONLY valid for the tested sample, please feedback to us within 15 working days if you have any question.)
2. SI  
The calibration results of this certificate can be traced back to the International System of Units (SI) units
3.  
Each certificate has a unique number. If replaced the certificate, the original certificate will be invalid once the new certificate number is issued.)
4. ~~06~~ " P" | " Pass" " F" | " Fail"  
In the datasheet, MPE & determination is only for reference, "P" represents "Pass" and "F" represents "Fail".)
5. /  
The results presented in this document apply only to the verified instrument.)
6.  
This certificate shall not be partly reproduced without written approval of the laboratory.)

: h, m 55C-7 D P S,,`0



Large stylized watermark 'P' on the left side of the page.



Result of Calibration

DAFCHGX002140003  
Report No.

3 , 3  
Page 3 of 3 Pages

1 (Appearance & Interaction):

M

